EXISTING CONCRETE BLABS

TRANSVERSE CONSTRUCTION OR CONTRACTION JOINTS

LONGITUDINAL CONSTRUCTION JOINTS

SPALL REPAIR
AREAS


SPALL DEPAIR RANDOM CRACK

SPALL DEPAIR AREAS


SPALL DEPAIR RANDOM CRACK

EXISTING OR PROPOSED ASPHALT SHOULDER

PLAN VIEW OF JOINTS, SPALL REPAIR, AND RANDOM CRACK REPAIR



DETAIL FOR PARTIAL DEPTH SPALL REPAIR AT TRANSVERSE JOINT



DETAIL FOR PARTIAL DEPTH SPALL REPAIR

GENERAL NOTES

RANDOM CRACK REPAIR

- (A) RANDOM CRACKS SHALL BE ROUTED OR CHIPPED TO A MINIMUM DIMENSION OF $\frac{1}{4}$ " WIDE AND $\frac{3}{8}$ " DEEP AND THEN SEALED.
- (B) IF HOT-POURED ELASTIC TYPE CONCRETE JOINT SEALANT IS USED TO SEAL RANDOM CRACKS, THEN ITEM NO. 502-08.04, SEALING RANDOM CRACKS (HOT POURED ELASTIC) PER LINEAR FOOT IS TO BE USED.
- © IF SILICONE SEALANT IS USED TO SEAL RANDOM CRACKS, THEN ITEM NO. 502-08.07, SEALING RANDOM CRACKS (SILICONE SEALANT) PER LINEAR FOOT IS TO BE USED.
- (D) ALL RANDOM CRACKS 1/8" OR GREATER ARE TO BE REPAIRED.

SPALL REPAIR

- E PARTIAL DEPTH SPALL REPAIR SHALL BE DONE ON LOW SPEED FACILITIES ONLY. USE FULL DEPTH PAVEMENT REPLACEMENT FOR HIGH SPEED FACILITIES, SUCH AS FREEWAYS AND EXPRESSWAYS.
- (F) ALL PARTIAL DEPTH SPALL REPAIR AREAS SHALL BE SAWED AND CHIPPED TO THE APPROXIMATE LINES SHOWN IN THE ABOVE DETAIL. ALL COSTS OF THIS WORK SHALL BE INCLUDED IN THE PRICE BID FOR ITEM NO. 502-07, SPALL REPAIR, PER SQUARE YARD.
- (G) BEFORE BEGINNING REPAIR PROCESS, EACH SPALL AREA SHALL BE CLEAN, DRY, AND FREE OF ANY FOREIGN MATERIAL.
- (H) IF DEPTH OF SPALL EXCEEDS 4" THEN IT SHALL BE MEASURED BY THE SQUARE YARD AND PAID FOR UNDER ITEM NO. 501-01, PORTLAND CEMENT CONCRETE PAVEMENT (REPLACEMENT). SEE PARTIAL SLAB REPAIR DETAILS ON STANDARD DRAWING NO. RP-J-23.

CROSS-REFERENCE DRAWINGS FOR THIS SHEET: RP-J-9, RP-J-23,

AND RP-J-25.

REV. 07-17-84: ADDED EXISTING AND PROPOSED LAYOUTS OF CONCRETE PAVEMENT REPLACEMENT. ADDED TIE

REV. 04-2-90: DREW NEW SHEET WHICH

NEW INFORMATION REGARDING JOINT

REV. 07-29-96: TRANSFERRED DETAILS REGARDING CONCRETE JOINT REPAIR TO

DRAWING NO. RP-J-25. ADDED DETAIL

FOR PARTIAL DEPTH SPALL REPAIR AT

REV. 05-27-01: CHANGED PAY ITEM IN

REV. 05-01-20: COMBINED GENERAL NOTES INTO ONE BLOCK AND RELETTERED NOTES.

GENERAL NOTES R2 AND R3.

REPAIR TO CONCUR WITH REVISED

REV. 12-18-94: MODIFIED SPALL REPAIR DETAIL AND GENERAL NOTES.

DRAWING NO. RP-J-9.

TRANSVERSE JOINT.

REDREW SHEET.

DRAWING NO. RP-J-23 REGARDING SPALL REPAIR, RANDOM CRACK REPAIR, AND JOINT REPAIR DETAILS. ADDED

INCLUDED INFORMATION PREVIOUSLY ON

BARS AND CHANGED NOTES.

☐ APPROVED BY FHWA

(ALL OTHERS APPROVED BY TDOT)

STATE OF TENNESSEE
STANDARD
DRAWING

CONCRETE
PAVEMENT
SPALL AND
RANDOM CRACK
REPAIR DETAILS

DEPARTMENT OF TRANSPORTATION

RP-J-24

NOT TO SCALE