



State/US Route or Road Name: SR-141 (Hartsville Pike)

Inspection Date: 3/10/19

Contract #: 111887 PIN: 129888.00 County: Wilson

TNR# 199888

**EPSC Inspection Report**

Did the contractor accompany the EPSC inspector on the inspection as required by SP107FP? Yes  No

Does the contractor agree with the findings noted below and on the attached TDEC form CN-1173 dated Yes ?  
 Yes  No  If no, it is the responsibly of the contractor to provide written comments that detail their disagreement with the noted findings.

Number of Corrective Actions	3
Number of Recurring Corr. Acts.	0
Number of Sediment Releases	0

Contractor's Signature: Daryl Allen Date: 3/10/19

Outfall # / STR or WTL #	Entry Type	App. Station # From/To	Date Last Disturbed	Stabilization Date / Type T = Temporary P = Permanent		Action Code	Action Required / Clarification	Object. Color Contrast (Y)	Sed. Release (Y)
1	CA	395+00 / 401+00	2/18/19	2/20/19	T	SR	EPSC measure needs to be installed, including permanent stabilization	N	Y
2	CA	414+00 / 418+50	2/18/19	2/20/19	T	SR	EPSC measure needs to be installed, including permanent stabilization	N	Y
3	CA	424+25/ 426+75	2/18/19	2/20/19	T	SR	EPSC measure needs to be installed, including permanent stabilization	N	Y

**Entry Type Codes**

- CA Corrective Action
- RCA Recurring Corrective Action
- FM Future Maintenance

- CE Install construction entrance/exit
- CL Clean out measure
- CO Outfall is closed
- CW Install concrete washout
- DC Implement dust control

**Action Codes**

- DIV Install diversion
- HV Install high visibility fence
- I Install measure
- LIT Pick up litter/debris
- PS Permanently stabilize area
- R Repair/Replace measure
- REM Remove measure
- SR Clean up sediment release\*
- TRAC Clean off tracking from road
- TS Temporarily stabilize area
- U Upgrade measure
- W Too wet to work

\*Approval from TDEC is needed prior to removal of sediment from a stream or wetland.