## STATE OF TENNESSEE DEPARTMENT OF CORRECTION

## INVITATION TO BID # 32947-13335 AMENDMENT # 1 FOR MCCX Guild Door Replacement

DATE: 05/15/2024

## ITB # 32947-13335 IS AMENDED AS FOLLOWS:

## 1. State responses to questions and comments in the table below amend and clarify this ITB.

Any restatement of ITB text in the Question/Comment column shall <u>NOT</u> be construed as a change in the actual wording of the ITB document.

| ITB<br>SECTION | PAGE<br># | QUESTION / COMMENT   | STATE RESPONSE   |
|----------------|-----------|--|--|
|                |           | 1. Door description calls for 7080 RR Brink lock. That is a mechanical lock. The drawing on page 7 calls for an electric lock (RR Brink 5020) as well as a key override, intercom, indicator light, and DPS. Which lock is required and are the additional items listed also required? | The correct lock is the 7080 RR Brink mechanical lock.   |
|                |           | 2. Sidelight description calls for 24" x 37" and 23" x 37" Level 3 3/8". Is this the same as the window referenced below?  Output  Description calls for a series of the same as the window referenced below?  | The sidelight measurement is 8"X22"X1/2" Polycarbonate.  The placement is 12-1/2" from top and 7-1/2" from right side of door. |
|                |           |  | Please see updated specs   |
|                |           | 3. Scope mentions windows that are 8' x 11'-2" (that seems huge) with detail on A-1. I did not see any window or sidelight details on A-1 (page 7). A frame elevation or photo might help to clarify.  | N/A refer to question 2  |
|                |           | <ol> <li>There is conflicting information on the glazing Level 3 – 3/8"     Polycarbonate (Lexan) and 13/16" laminated (Glass Clad Polycarbonate). Both are Level III products just different types of glazing. Grade 1 is also mentioned. See attached brochure.</li> </ol>           | N/A refer to question 2  |
|                |           | A-1 also refers to floor and wall work. Except for grout filling frames, Is any additional   | A-1 will be removed from the specifications as the drawings are not  |

| ITB<br>SECTION | PAGE<br># | QUESTION / COMMENT   | STATE RESPONSE   |
|----------------|-----------|--|--|
|                |           | concrete work (cutting or pouring) required as part of this scope? | accurate. No additional concrete work other than filling door frames will be required. |

2. Delete ITB attachment MCCX Guild Door Specifications in its entirety and insert the following in its place (any sentence or paragraph containing revised or new text is highlighted):

MCCX Guild Door Final Specs v2

**3.** <u>ITB Amendment Effective Date</u>. The revisions set forth herein shall be effective upon release. All other terms and conditions of this ITB not expressly amended herein shall remain in full force and effect.