

PERMIT #: 66554

SAMPLE COMPLETED  
BUILDING PERMIT

State of Tennessee

Department of Commerce & Insurance  
State Fire Marshal

RESIDENTIAL

BUILDING PERMIT

Permittee: John Public

DATE ISSUED: 08/31/2010

Permit shall expire 2 years from date of issue or upon issuance of Certificate of Occupancy unless an extension is granted by the State Fire Marshal's Office

Construction Location

Address: 123 Main St

City: Alamo

County: Crockett

ZIP Code: 38001

Description of work to be performed:

- New Construction Heated Sq Ft: 1150 Unheated Sq Ft: 400
- Addition Heated Sq Ft: Unheated Sq Ft:
- Site (Modular/Manufactured)

- Foundation type:
- Conventional
  - Monolith Pour Slab
  - Slab other than Monolith Pour

Inspections

Inspections do not warrant workmanship. Any inspection performed by any employee, agent or contractor of the State of Tennessee are performed solely for the purposes of enforcement of the applicable building codes which may utilize a spot check performance standard, and do not provide comprehensive home inspection services, which are the responsibility of the owner.

<b>Footing or monolith slab:</b>	Date:	<input type="checkbox"/> PASS	<input type="checkbox"/> FAIL	by:
<b>Slab other than monolith:</b>	Date:	<input type="checkbox"/> PASS	<input type="checkbox"/> FAIL	by:
<b>Rough In:</b>	Date:	<input type="checkbox"/> PASS	<input type="checkbox"/> FAIL	by:
<b>Final:</b>	Date:	<input type="checkbox"/> PASS	<input type="checkbox"/> FAIL	by:
<b>Other (please list):</b>	Date:	<input type="checkbox"/> PASS	<input type="checkbox"/> FAIL	by:
	Date:	<input type="checkbox"/> PASS	<input type="checkbox"/> FAIL	by:
	Date:	<input type="checkbox"/> PASS	<input type="checkbox"/> FAIL	by:

Call 1-866-283-6191 and select Option 2 to schedule an inspection. Only permittee may schedule inspection. Permittee is responsible for scheduling all inspections.

Note: Only one re-inspection will be conducted during building inspection process unless an additional inspection authorization is obtained upon payment of a fee of \$100 per additional inspection. You must pay \$100 to an authorized issuing agent prior to requesting a second re-inspection.